EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	19758	((455/41.1,41.2,41.3,39,426.1, 426.2) or (370/278,282,343,352, 389,394,338,465,480) or (219/130.01,130.05,130.21,125.1, 132,137R) or (700/3,9,35,108, 117,121,145,162,169)).CCLS.	US-PGPUB; USPAT	OR	OFF	2005/09/20 13:20
S2	3	(("6624388") or ("6479792") or ("6600726")).PN.	US-PGPUB; USPAT	OR	OFF	2006/07/17 15:53
S3	49	welding near8 wireless	US-PGPUB; USPAT	OR	OFF	2006/08/17 18:04
S4	19758	((455/41.1,41.2,41.3,39,426.1, 426.2) or (370/278,282,343,352, 389,394,338,465,480) or (219/130.01,130.05,130.21,125.1, 132,137R) or (700/3,9,35,108, 117,121,145,162,169)).CCLS.	US-PGPUB; USPAT	OR	OFF	2005/09/21 11:50
S5	13	S3 and S4	US-PGPUB; USPAT	OR	OFF	2005/09/21 11:50
S6	9	("5463555" "5805442" "5808885" "5850066" "5859847" "6002104" "6018729" "6040555" "6087627").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/04/13 17:07
S7	22464	((455/41.1,41.2,41.3,39,426.1, 426.2) or (370/278,282,343,352, 389,394,338,465,480) or (219/130.01,130.05,130.21,125.1, 132,137R) or (700/3,9,35,108, 117,121,145,162,169)).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/04/13 17:07
S8	1912	weld\$3 near4 (communicat\$3 or transmit\$4 or send\$3) near4 weld\$3	US-PGPUB; USPAT	OR	ON	2006/04/13 17:08
S9	179	S7 and S8	US-PGPUB; USPAT	OR	ON	2006/04/13 17:08
S10	1	("6624388").PN.	US-PGPUB; USPAT	OR	OFF	2006/07/17 15:53
S11	56	welding near8 wireless	US-PGPUB; USPAT	OR	OFF	2006/07/23 12:30
S12	23989	((455/41.1,41.2,41.3,39,426.1, 426.2) or (370/278,282,343,352, 389,394,338,465,480) or (219/130.01,130.05,130.21,125.1, 132,137R) or (700/3,9,35,108, 117,121,145,162,169)).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/07/23 12:30

EAST Search History

		·				
S13	24357	((455/41.1,41.2,41.3,39,426.1, 426.2) or (370/278,282,343,352, 389,394,338,465,480) or (219/130.01,130.05,130.21,125.1, 132,137R) or (700/3,9,35,108, 117,121,145,162,169)).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/08/17 15:10
S14	61	welding near8 wireless	US-PGPUB; USPAT	OR	OFF	2006/08/17 15:11
S15	2002	weld\$3 near4 (communicat\$3 or transmit\$4 or send\$3) near4 weld\$3	US-PGPUB; USPAT	OR	ON	2006/08/17 15:11
S16	187	S13 and S15	US-PGPUB; USPAT	OR	OFF	2006/08/17 15:11
S17	24357	((455/41.1,41.2,41.3,39,426.1, 426.2) or (370/278,282,343,352, 389,394,338,465,480) or (219/130.01,130.05,130.21,125.1, 132,137R) or (700/3,9,35,108, 117,121,145,162,169)).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/08/17 18:04
S18	1	welding near8 "spread spectrum"	US-PGPUB; USPAT	OR	ON	2006/08/17 18:07
S19	1	welding near18 "spread spectrum"	US-PGPUB; USPAT	OR	ON	2006/08/17 18:08
S20	2	welding near18 "direct sequence"	US-PGPUB; USPAT	OR	ON	2006/08/17 18:08
S21	. 1	welding near18 hopping	US-PGPUB; USPAT	OR	ON	2006/08/17 18:08
S22	1	welding near8 error near4 threshold near7 fail near3 safe	US-PGPUB; USPAT	OR	ON	2006/08/17 18:12
S23	1	welding near8 error near4 threshold near7 safe	US-PGPUB; USPAT	OR	ON	2006/08/17 18:12
S24	1	welding near8 threshold near7 safe	US-PGPUB; USPAT	OR	ON	2006/08/17 18:12
S25	1	welding near15 threshold near7 safe	US-PGPUB; USPAT	OR	ON	2006/08/17 18:12
S26	1	welding near15 threshold near7 fail	US-PGPUB; USPAT	OR	ON	2006/08/17 18:13
S27	12	welding near15 error near7 fail	US-PGPUB; USPAT	OR	ON	2006/08/17 18:49
S28	16	weld\$3 near15 error near7 fail	US-PGPUB; USPAT	OR	ON	2006/08/17 18:49
S29	4	S28 not S27	US-PGPUB; USPAT	OR	ON	2006/08/17 18:49